

LT-100 LATERAL HEADER TILT SYSTEM CUSTOMER ORDERING GUIDE (FOR COMBINE ONLY)

CHOOSE YOUR COMBINE'S MODEL AND SERIAL NUMBER, THEN FOLLOW THE COLUMN DOWN TO YOUR JD AND HILCO PRICING



HILLCO TECHNOLOGIES

Hillco Technologies, Inc. Nezperce, ID
Ph 800-937-2481 Fax 208-937-2280 www.hillcotechologies.com

This ordering guide covers equipping the <u>combine only</u> with a Hillco LT-100.				John Deere Combine Model & Serial Number Breaks																									
				SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE									
Combine Requirements 1. All 9000, 9010, CTS & CTS II Combines must have Dial-A-Matic. 2. All 50 Series Combines must have Header Height Sensing (HHS), Active Header Control (AHC) and In-Cab Display.				9400 (- 660100)	9400 (660101-)	9410	9450 (- 695100)	9450 (695101-)	9500 (- 660200)	9500 (660201-)	9510	9550 (- 695200)	9550 (695201-)	9600 (- 660300)	9600 (660301-)	9610	9650 (- 695300)	9650 (695301-)	CTS (- 660400)	CTS (660401-)	CTSII	9650CTS (- 695400)	9650CTS (695401-)	9650STS (- 695500)	9650STS (695501-)	9750STS (- 695600)	9750STS (695601-)		
				Hillco Parts - Jan, 2011																									
Part Number	Description	List Price	Qty.																										
LT-100	KIT	\$5,995.00	1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
LTA-243931	HARNESS	\$375.00	1	X					X				X					X											
Hillco Parts Total (List Price) does not include freight or installation				\$6,370.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$6,370.00	\$5,995.00	\$5,995.00	\$5,995.00	\$6,370.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$6,370.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	\$5,995.00	
John Deere Parts - January, 2011																													
Part Number	Description	List Price	Qty.																										
AH145061	HANDLE	\$37.61	1	X	X	X			X	X	X			X	X	X			X	X	X								
AH145060	SWITCH	\$80.66	1	X	X	X			X	X	X			X	X	X			X	X	X								
AH215463	HANDLE	\$813.70	1				X				X					X						X		X		X			
AH207160	HANDLE	\$803.40	1					X					X									X		X		X		X	
AH220605	BOARD	\$1,004.24	1				X(1)	X(1)				X(1)	X(1)			X(1)	X(1)					X(1)	X(1)	X(1)	X(1)	X(1)	X(1)	X(1)	
AH137147	BOARD	\$654.05	1	X	X	X			X	X	X			X	X	X			X	X	X								
H159740	LABEL	\$8.19	1		X	X				X	X			X	X					X	X								
AH111705	SWITCH	\$55.01	1		X	X				X	X			X	X					X	X								
H143918	ACTUATOR	\$2.44	1		X	X				X	X			X	X					X	X								
H207776	SLAT	\$29.63	5*											X	X	X			X	X	X								
H206436	SLAT	\$34.77	3*	X	X	X	X	X	X	X	X	X	X	X	X	X			X	X	X	X	X	X	X	X	X	X	
Prices are subject to change without notice. These are the John Deere List Prices as of 1/11 as per jdparts.deere.com.				\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,290.47	\$6,981.11	\$6,981.11	\$7,961.09	\$7,950.79	\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,917.25	\$7,906.95	\$7,917.25	\$7,906.95		
* Quantities may vary due to differences in feeder chains.																													
John Deere Parts Total (List Price)				\$876.63	\$942.27	\$942.27	\$1,922.25	\$1,911.95	\$876.63	\$942.27	\$942.27	\$1,922.25	\$1,911.95	\$920.47	\$986.11	\$986.11	\$1,966.09	\$1,955.79	\$876.63	\$942.27	\$942.27	\$1,922.25	\$1,911.95	\$1,922.25	\$1,911.95	\$1,922.25	\$1,911.95		
Price are subject to change without notice.																													
Total Hillco & John Deere Parts (List Price) does not include freight or installation				\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,290.47	\$6,981.11	\$6,981.11	\$7,961.09	\$7,950.79	\$7,246.63	\$6,937.27	\$6,937.27	\$7,917.25	\$7,906.95	\$7,917.25	\$7,906.95	\$7,917.25	\$7,906.95		
Other Costs Not Included:				NOTE																									
Installation Labor Est. 10 hrs.				(X1) - ALL 50 SERIES COMBINES: In order to determine the correct pricing and required JD parts, it is necessary to physically look at the circuit board for AHC/HHR to see if it is part number AH172613, AH206189, AH217993 or AH220605. The circuit board is located in the central electronics modular next to the door of the cab. If your 50 series combine <u>does not</u> have the correct circuit board, then that requires the purchase of the AH220605 circuit board, and the total price is correct. If your 50 series combine <u>does</u> have the AH172613, AH206189, AH217993 or AH220605 circuit board then subtract \$1,004.24 from the total and do not purchase the circuit board. With the basic LT-100 installation the in-cab header angle display will not function. This display can be activated with the installation of additional JD parts. Contact Hillco for details.																									
Freight: FOB Colona, IL.= \$90																													
Freight to Your Location = Contact Hillco 800-937-2461																													