LT-200 LATERAL HEADER TILT SYSTEM CUSTOMER ORDERING GUIDE (FOR COMBINE ONLY)

CHOOSE YOUR COMBINE'S MODEL AND SERIAL NUMBER, THEN FOLLOW THE COLUMN DOWN TO YOUR JD AND HILLCO PRICING

This ordering guide covers equipping the combine only with a Hillco LT-200.

Combine Requirements

1. All 9000, 9010, CTS & CTS II Combines must have Dial-A-Matic.
2. All 50 Series Combines must have Header Height Sensing (HHS), Active Header Control (AHC) and In-Cab Display.

	John Deere Combine Model & Serial Number Breaks																							
				SEE NOTE					SEE NOTE					SEE NOTE					SEE NOTE		SEE NOTE		SEE NOTE	
	9400 (- 660100)	**9400 (660101-)**	**9410**	**9450 (-695100)**	**9450 (695101-)**	**9500 (-660200)**	**9500 (660201-)**	**9510**	**9550 (-695200)**	**9550 (695201-)**	**9600 (-660300)**	**9600 (660301-)**	**9610**	**9650 (-695300)**	**9650 (695301-)**	**CTS (-660400)**	**CTS (660401-)**	**CTSII**	**9650CTS (-695400)**	**9650CTS (6954010-)**	**9650STS (-695500)**	**9650STS (695501-)**	**9750STS (-695600)**	**9750STS (695601-)**
Hillco Parts - Jan, 2011																								
Part Number / Description / List Price / Qty.																								
LT-200 KIT $7,550.00 1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
LTA-243931 HARNESS $375.00 1	X					X					X					X								
Hillco Parts Total (List Price) does not include freight or installation	**$7,925.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,925.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,925.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,925.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**	**$7,550.00**
John Deere Parts - January, 2011																								
Part Number / Description / List Price / Qty.																								
AH145061 HANDLE $37.61 1	X	X	X			X	X	X			X	X	X			X	X	X						
AH145060 SWITCH $80.66 1	X	X	X			X	X	X			X	X	X			X	X	X						
AH215463 HANDLE $813.70 1				X					X					X					X		X		X	
AH207160 HANDLE $803.40 1					X					X					X					X		X		X
AH220605 BOARD $1,004.24 1				X(1)	X(1)				X(1)	X(1)				X(1)	X(1)				X(1)	X(1)	X(1)	X(1)	X(1)	X(1)
AH137147 BOARD $654.05 1	X	X	X			X	X	X			X	X	X			X	X	X						
H159740 LABEL $8.19 1		X	X				X	X				X	X				X	X						
AH111705 SWITCH $55.01 1		X	X				X	X				X	X				X	X						
H143918 ACTUATOR $2.44 1		X	X				X	X				X	X				X	X						
H207776 SLAT $29.63 5*											X	X	X	X	X									
H206436 SLAT $34.77 3*	X	X	X	X	X	X	X	X	X	X						X	X	X	X	X	X	X	X	X
Prices ar subject to change without notice. These are the John Deere List Prices as of 1/11 as per jdparts.deere.com. * Quanities may vary due to differences in feeder chains. **John Deere Parts Total (List Price)**	**$876.63**	**$942.27**	**$942.27**	**$1,922.25**	**$1,911.95**	**$876.63**	**$942.27**	**$942.27**	**$1,922.25**	**$1,911.95**	**$920.47**	**$986.11**	**$986.11**	**$1,966.09**	**$1,955.79**	**$876.63**	**$942.27**	**$942.27**	**$1,922.25**	**$1,911.95**	**$1,922.25**	**$1,911.95**	**$1,922.25**	**$1,911.95**
Price are subject to change without notice. **Total Hillco & John Deere Parts (List Price)** does not include freight or installation	**$8,801.63**	**$8,492.27**	**$8,492.27**	**$9,472.25**	**$9,461.95**	**$8,801.63**	**$8,492.27**	**$8,492.27**	**$9,472.25**	**$9,461.95**	**$8,845.47**	**$8,536.11**	**$8,536.11**	**$9,516.09**	**$9,505.79**	**$8,801.63**	**$8,492.27**	**$8,492.27**	**$9,472.25**	**$9,461.95**	**$9,472.25**	**$9,461.95**	**$9,472.25**	**$9,461.95**

Other Costs Not Included:

Installation Labor Est. 10 hrs.

Frieght: FOB Colona, IL.= $90

Freight to Your Location = Contact Hillco 800-937-2461

NOTE

X(1) - ALL 50 SERIES COMBINES: In order to determine the correct pricing and required JD parts, it is necessary to physically look at the circuit board for AHC/HHR to see if it is part number AH172613, AH206189, AH217993 or AH220605. The circuit board is located in the central electronics modual next to the door of the cab. If your 50 series combine does not have the correct circuit board, then that requires the purchase of the AH220605 circiut board, and the total price is correct. If your 50 series combine does have the AH172613, AH206189, AH217993 or AH220605 circuit board then subtract $1,004.24 from the total and do not purchace the circuit board. With the basic LT-200 installation the in-cab header angle display will not function. This display can be activated with the installation of additional JD parts. Contact Hillco for details.

D062508SZ04F

HILLCO TECHNOLOGIES
Hillco Technologies, Inc. Nezperce, ID
Ph 800-937-2461 Fx 208-937-2280 www.hillcotechnologies.com