



Hillco Technologies, Inc.
 1010 1st Avenue
 Nezperce, ID 83543-5062
 Phone 208-937-2461
 Fax 208-937-2280

2017

CUSTOMER PRICING FOR LATERAL HEADER TILT SYSTEMS AND HEADER CONVERSION KITS

LATERAL HEADER TILT SYSTEMS			
Combine Model Number (required) _____	Combine Serial Number (required) _____		
Feeder Chain Type (LT100 & LT200 only) Check one: Light Duty - CA550 <input type="checkbox"/> Heavy Duty - CA550HD or CA557 <input type="checkbox"/>			
LT-100 & 200 - Auto-Lateral Tilt Cable (Req for pre-Contour Master combines)		LTA-243931	\$380.00 <input type="checkbox"/>
<i>Please refer to the LT-100 or LT-200 Lateral Header Tilt System Dealer Ordering Guide to see which combines require the Auto-Lateral Tilt Cable</i>			
LT-100 - Fits all 9000 Series, 10 Series, CTS, CTS II, 50 Series John Deere combines. Upgrades combine with 4° of lateral tilt.		Hillco Part # LT-100	List Price \$6,295.00 <input type="checkbox"/>
LT-200 - Fits all 9000 Series, 10 Series, CTS, CTS II, 50 Series John Deere combines. Upgrades combine with 4° of lateral tilt and 9° fore & aft tilt.		Hillco Part # LT-200	List Price \$7,885.00 <input type="checkbox"/>
<i>The LT-100 and LT-200 are approved for all John Deere heads up to the weight limit of 7440 lbs. This excludes John Deere 635D, 640D, 612C, and 612C Stalkmaster heads. The LT-200 is not approved for 606C and 606C Stalkmaster heads due to driveline angle. Heads exceeding 7440 lbs or heads not approved by Hillco may void the warranty. For non John Deere heads and platforms contact Hillco for further information .</i>			

HEADER CONVERSION KITS							
For 9000 & 10 Series combines w/ Hillco LT-100 & LT-200 Lateral Header Tilt Systems		WITH DRIVELINES 1-1/8 Hex Quick Couple x 1-1/8 Hex Clamping			WITHOUT DRIVELINES		
Header Type	Header Model Number	Hillco Part #	List Price	Qty Ordered	Hillco Part #	List Price	Qty Ordered
Corn	594, 643, 644, 645, 692, 693, 694, 843, 844, 893, 894, 1092, 1243, 1290, 1291, 1293	LTA-9300	\$1,035.00	<input type="checkbox"/>	LTA-9301	\$307.00	<input type="checkbox"/>
Flex and Rigid	915, 918, 920, 922, 925, 930	LTA-9000	\$1,410.00	<input type="checkbox"/>	LTA-9001	\$680.00	<input type="checkbox"/>
Row Crop	653A, 853A, 854A, 1253A	LTA-9300	\$1,035.00	<input type="checkbox"/>	LTA-9301	\$307.00	<input type="checkbox"/>
Pick-Up	914	LTA-9100	\$1,025.00	<input type="checkbox"/>	NOT AVAILABLE		
Drivelines Only	1-1/8 Hex Quick Couple Yoke x 1-1/8 Hex Clamping Yoke x 24" CPC	136481 (1 Shaft)	\$364.00	<input type="checkbox"/>			

For All 50 & 60 Series combines w/ or w/o Contour Master and 9000 & 10 Series combines w/ Contour Master		WITH DRIVELINES 1-3/8 21T Quick Couple x 1-1/8 Hex Clamping			WITHOUT DRIVELINES		
Header Type	Header Model Number	Hillco Part #	List Price	Qty Ordered	Hillco Part #	List Price	Qty Ordered
Corn	594, 643, 644, 645, 692, 693, 694, 843, 844, 893, 894, 1092, 1243, 1290, 1291, 1293	LTA-9350	\$1,035.00	<input type="checkbox"/>	LTA-9301	\$307.00	<input type="checkbox"/>
Flex and Rigid	915, 918, 920, 922, 925, 930	LTA-9050	\$1,410.00	<input type="checkbox"/>	LTA-9001	\$680.00	<input type="checkbox"/>
Row Crop	653A, 853A, 854A, 1253A	LTA-9350	\$1,035.00	<input type="checkbox"/>	LTA-9301	\$307.00	<input type="checkbox"/>
Pick-Up	914	LTA-9145	\$1,025.00	<input type="checkbox"/>	NOT AVAILABLE		
Drivelines Only	1-3/8-21 Tooth Splined Quick Couple Yoke x 1-1/8 Hex Clamping Yoke x 24" CPC	242411 (1 Shaft)	\$364.00	<input type="checkbox"/>	Prices subject to change without notice.		

Looking for Header Conversion Kits for headers not shown above? Call Hillco 1-208-937-2461

LT-200 LATERAL HEADER TILT SYSTEM CUSTOMER ORDERING GUIDE (FOR COMBINE ONLY)

CHOOSE YOUR COMBINE'S MODEL AND SERIAL NUMBER, THEN FOLLOW THE COLUMN DOWN TO YOUR JD AND HILCO PRICING



HILCO TECHNOLOGIES

Hilco Technologies, Inc. Nezperce, ID
Ph 800-937-2461 Fx 208-937-2280 www.hilcotechologies.com

This ordering guide covers equipping the combine only with a Hilco LT-200.				John Deere Combine Model & Serial Number Breaks																								
				SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE		SEE NOTE								
Combine Requirements 1. All 9000, 9010, CTS & CTS II Combines must have Dial-A-Matic. 2. All 50 Series Combines must have Header Height Sensing (HHS), Active Header Control (AHC) and In-Cab Display.				9400 (- 660100)	9400 (660101-)	9410	9450 (- 695100)	9450 (695101-)	9500 (- 660200)	9500 (660201-)	9510	9550 (- 695200)	9550 (695201-)	9600 (- 660300)	9600 (660301-)	9610	9650 (- 695300)	9650 (695301-)	CTS (- 660400)	CTS (660401-)	CTSII	9650CTS (- 695400)	9650CTS (6954010-)	9650STS (- 695500)	9650STS (695501-)	9750STS (- 695600)	9750STS (695601-)	
Hilco Parts - 2017																												
Part Number	Description	List Price	Qty.																									
LT-200	KIT	\$7,885.00	1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
LTA-243931	HARNESS	\$380.00	1	X					X				X					X										
Hilco Parts Total (List Price) does not include freight or installation				\$8,265.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$8,265.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$8,265.00	\$7,885.00	\$7,885.00	\$7,885.00	\$8,265.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	\$7,885.00	
John Deere Parts - 2017																												
Part Number	Description	List Price	Qty.																									
AH145061	HANDLE	\$42.04	1	X	X	X			X	X	X			X	X	X		X	X	X								
AH145060	SWITCH	\$81.69	1	X	X	X			X	X	X			X	X	X		X	X	X								
AH215463	HANDLE	\$924.09	1				X					X									X		X		X			
AH207160	HANDLE	\$912.42	1					X				X										X		X		X		
AH220605	BOARD	\$1,104.49	1				X(1)	X(1)				X(1)	X(1)				X(1)	X(1)			X(1)	X(1)	X(1)	X(1)	X(1)	X(1)	X(1)	
AH137147	BOARD	\$664.16	1	X	X	X			X	X	X			X	X	X		X	X	X								
H159740	LABEL	\$8.34	1		X	X				X	X			X	X	X					X	X	X					
AH111705	SWITCH	\$53.25	1		X	X				X	X			X	X					X	X							
H143918	ACTUATOR	\$2.23	1		X	X				X	X			X	X					X	X							
H207776	SLAT	\$26.78	5*											X	X	X		X	X									
H206436	SLAT	\$31.43	3*	X	X	X	X	X	X	X	X	X	X					X	X	X	X	X	X	X	X	X	X	
Prices are subject to change without notice. These are the John Deere List Prices as of 6/16 as per jdparts.deere.com.				\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$921.79	\$985.61	\$985.61	\$2,162.48	\$2,150.81	\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$2,122.87	\$2,111.20	\$2,122.87	\$2,111.20	
* Quantities may vary due to differences in feeder chains.																												
John Deere Parts Total (List Price)				\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$921.79	\$985.61	\$985.61	\$2,162.48	\$2,150.81	\$882.18	\$946.00	\$946.00	\$2,122.87	\$2,111.20	\$2,122.87	\$2,111.20	\$2,122.87	\$2,111.20	
Price are subject to change without notice.																												
Total Hilco & John Deere Parts (List Price) does not include freight or installation				\$9,147.18	\$8,831.00	\$8,831.00	\$10,007.87	\$9,996.20	\$9,147.18	\$8,831.00	\$8,831.00	\$10,007.87	\$9,996.20	\$9,186.79	\$8,870.61	\$8,870.61	\$10,047.48	\$10,035.81	\$9,147.18	\$8,831.00	\$8,831.00	\$10,007.87	\$9,996.20	\$10,007.87	\$9,996.20	\$10,007.87	\$9,996.20	
Other Costs Not Included:				NOTE																								
Installation Labor Est. 10 to 15 hrs.				X(1) - ALL 50 SERIES COMBINES: In order to determine the correct pricing and required JD parts, it is necessary to physically look at the circuit board for AHC/HHR to see if it is part number AH172613, AH206189, AH217993 or AH220605. The circuit board is located in the central electronics module next to the door of the cab. If your 50 series combine <u>does not</u> have the correct circuit board, then that requires the purchase of the AH220605 circuit board, and the total price is correct. If your 50 series combine <u>does</u> have the AH172613, AH206189, AH217993 or AH220605 circuit board then subtract \$1,104.49 from the total and do not purchase the circuit board. With the basic LT-200 installation the in-cab header angle display will not function. This display can be activated with the installation of additional JD parts. Contact Hilco for details.																								
Freight to Your Location = Contact Hilco 800-937-2461																												